

# **HISTORIC AMERICAN ENGINEERING RECORD**

## **INDEX TO PHOTOGRAPHS**

ORTONA LOCK, LOCK NO. 2

HAER FL-19-A

Caloosahatchee River, Cross-State Canal, Okeechobee Intracoastal

Waterway

Ortona vicinity

Glades County

Florida

## **INDEX TO BLACK AND WHITE PHOTOGRAPHS**

Richard T Bryant, photographer, July 2000

FL-19-A-1	VIEW FROM DOWNSTREAM OF LOWER (WEST) LOCK GATE AND NORTHWEST AND SOUTHWEST CONTROL HOUSES AND TIMBER GUIDE WALLS, BUILDINGS NO. 52 AND NO. 53 IN BACKGROUND, VIEW TOWARDS NORTHEAST
FL-19-A-2	VIEW FROM DOWNSTREAM OF LOWER (WEST) LOCK GATE AND NORTHWEST AND SOUTHWEST CONTROL HOUSES AND TIMBER GUIDE WALL ON LEFT, VIEW TOWARD EAST
FL-19-A-3	VIEW OF LOWER (WESTERN) INTERIOR SOUTHERN LOCK WALL, SOUTHWEST CONTROL HOUSE IN BACKGROUND, AND LOCK DRAINED FOR REPAIRS, PUMP MECHANISM, VIEW TOWARDS SOUTHEAST
FL-19-A-4	VIEW OF LOWERMOST (WESTERNMOST) INTERIOR SOUTHERN LOCK WALL, SPILLWAY CHANNEL IN BACKGROUND, VIEW TOWARDS SOUTH
FL-19-A-5	OBLIQUE VIEW OF SOUTH AND EAST SIDES OF NORTHWEST CONTROL HOUSE AND INTERIOR OF CLOSED LOWER GATES WHILE LOCK DRAINED, VIEW TOWARDS NORTHWEST

ORTONA LOCK, LOCK NO. 2

HAER FL-19-A

INDEX TO PHOTOGRAPHS

(Page 2)

FL-19-A-6	VERTICAL OBLIQUE VIEW OF NORTH AND EAST SIDES OF SOUTHWEST CONTROL HOUSE AND INTERIOR OF CLOSED LOWER GATES WHILE LOCK DRAINED, VIEW TOWARDS SOUTHWEST
FL-19-A-7	PLANAR VIEW OF INTERIOR OF OPEN SOUTH UPPER (EAST) GATE OF LOCK, LOCK DRAINED AND UNDER REPAIR, SOUTHEAST CONTROL HOUSE AND SPILLWAY IN BACKGROUND, VIEW TOWARDS SOUTH
FL-19-A-8	PLANAR VIEW OF INTERIOR OF OPEN NORTH UPPER (EAST) GATE OF LOCK, LOCK DRAINED AND UNDER REPAIR, NORTHEAST CONTROL HOUSE AND LOCKMASTER'S OFFICE (BUILDING NO. 51) IN BACKGROUND, VIEW TOWARDS NORTH
FL-19-A-9	PLANAR VIEW OF INTERIOR WALL OF SOUTH SIDE OF LOCK, SPILLWAY IN BACKGROUND TO LEFT, EAST END, VIEW TOWARDS SOUTH
FL-19-A-10	PLANAR VIEW OF INTERIOR WALL OF SOUTH SIDE OF LOCK, MIDDLE-EAST SECTION, VIEW TOWARDS SOUTH
FL-19-A-11	PLANAR VIEW OF INTERIOR WALL OF SOUTH SIDE OF LOCK, MIDDLE SECTION, VIEW TOWARDS SOUTH
FL-19-A-12	PLANAR VIEW OF INTERIOR WALL OF SOUTH SIDE OF LOCK, MIDDLE-WEST SECTION, VIEW TOWARDS SOUTH
FL-19-A-13	PLANAR VIEW OF INTERIOR WALL OF SOUTH SIDE OF LOCK, WEST END, SOUTHWEST CONTROL HOUSE ON RIGHT, VIEW TOWARDS SOUTH
FL-19-A-14	VIEW OF LOWERMOST (WESTERNMOST) INTERIOR NORTHERN LOCK WALL, WITH BUILDING NO. 53 IN BACKGROUND, VIEW TOWARDS NORTH
FL-19-A-15	PLANAR VIEW OF INTERIOR OF LOWER (WEST) LOCK WALL, OPEN LOCK GATE, AND SOUTH SIDE OF NORTHWEST CONTROL HOUSE, VIEW TOWARDS NORTH
FL-19-A-16	PLANAR VIEW OF INTERIOR WALL OF NORTH SIDE OF LOCK, WEST END, VIEW TOWARDS NORTH

ORTONA LOCK, LOCK NO. 2

HAER FL-19-A

INDEX TO PHOTOGRAPHS

(Page 3)

FL-19-A-17	PLANAR VIEW OF INTERIOR WALL OF NORTH SIDE OF LOCK, MIDDLE-WEST END, BUILDING NO. 52 IN BACKGROUND, VIEW TOWARDS NORTH
FL-19-A-18	PLANAR VIEW OF INTERIOR WALL OF NORTH SIDE OF LOCK, MIDDLE-EAST END, BUILDINGS NO. 51 AND NO. 52 IN BACKGROUND, VIEW TOWARDS NORTH
FL-19-A-19	PLANAR VIEW OF INTERIOR WALL OF NORTH SIDE OF LOCK, EAST END, BUILDING NO. 51 IN BACKGROUND, VIEW TOWARDS NORTH
FL-19-A-20	VIEW OF SPILLWAY FROM UPSTREAM NORTH BANK, VIEW TOWARDS SOUTHWEST
FL-19-A-21	VIEW OF SPILLWAY FROM DOWNSTREAM NORTH BANK, VIEW TOWARDS SOUTHEAST
FL-19-A-22	VIEW OF SPILLWAY FROM FURTHER DOWNSTREAM ON SOUTH BANK, VIEW TOWARDS NORTHEAST
FL-19-A-23	VIEW OF SPILLWAY FROM DOWNSTREAM SOUTH BANK, VIEW TOWARDS NORTH
FL-19-A-24	DETAIL OF SECOND GATE FROM NORTH SIDE, LOOKING DOWN AT GATE MECHANISM, VIEW TOWARDS DOWNSTREAM (WEST)